

Dunbarton Pines Homeowners' Association – Main Commons Area


Existing Pathways



Ref	Findings
1	Potential archway and benches
2	Requires clearing
3	Requires clearing
4	West Path ends at property backyard – needs to be rerouted into main commons area
5	Initial path from West Path has been groomed, deteriorates as path approaches South Path
6	Needs clearing and grooming
7	Needs expanding
8	Potential pavilion site
9	Underbrush needs clearing; plantings may be need to north and south of entrance

Dunbarton Pines Homeowners' Association – Main Commons Area

Existing Pathways



Ref	Findings
1	Potential archway and benches
2	Requires clearing
3	Requires clearing
4	West Path ends at property backyard – needs to be rerouted into main commons area
5	Initial path from West Path has been groomed, deteriorates as path approaches South Path
6	Needs clearing and grooming
7	Needs expanding
8	Potential pavilion site
9	Underbrush needs clearing; plantings may be needed to north and south of entrance